

**Flood Control Project Maintenance
Levee Inspections****2014 Channel Summary Report****Overall Unit and Item Ratings****DWR Sutter Maintenance Yard**

Big Chico Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Lindo Channel & Sandy Gulch

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Little Chico Creek

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	M
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance**Unit Cover Sheet****2014 Channel Inspection Results****DWR Sutter Maintenance Yard**

Channel
Big Chico Creek

Channel Rating	A
Date of Inspection	07/16/2014
DWR Inspector	Matthew Hoffman
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View

Big Chico Creek Control Structure / Up

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_1			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2014_NA0060_5_1_20140721_00013.jpg



This is the upstream side of the structure.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_2			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_3			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View

Big Chico Creek Control Structure / Up (cont)

Rating **	A	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_4			

Action/Comments

Inspector Comments: Riprap is visible and appears properly maintained.

No Photos

Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_5			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Big Chico Creek Control Structure / Down

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_6			

Action/Comments

Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.

Photo 1 of 1 : CH_2014_NA0060_5_6_20140721_00014.jpg



Downstream side of the structure.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View				
Big Chico Creek Control Structure / Down (cont)				
Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_8			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	A	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_9			
Action/Comments				
Inspector Comments: Riprap is visible and appears properly maintained.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View				
Big Chico Creek Control Structure / Down (cont)				
Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		39.761840 °
Category	Rivers, Channels & Designated Flood			-121.792590 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_10			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Manzanita Ave. / Up				
Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		39.758260 °
Category	Rivers, Channels & Designated Flood			-121.795380 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_11			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2014_NA0060_5_11_20140721_00015.jpg



This photo is looking upstream on Manzanita Ave.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		39.758260 °
Category	Rivers, Channels & Designated Flood			-121.795380 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_12			
Action/Comments				
Inspector Comments: Shoaling or sedimentation was observed. Does not seem to impede flow.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View

Manzanita Ave. / Up (cont)

Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		39.758260 °
Category	Rivers, Channels & Designated Flood			-121.795380 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_13			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		39.758260 °
Category	Rivers, Channels & Designated Flood			-121.795380 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_14			
Action/Comments				
Inspector Comments: Riprap is visible and appears properly maintained.				

No Photos

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		39.758260 °
Category	Rivers, Channels & Designated Flood			-121.795380 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_15			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View

Manzanita Ave. / Down

Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		39.758260 °
Category	Rivers, Channels & Designated Flood			-121.795380 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_16			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2014_NA0060_5_16_20140721_00016.jpg



This photo is looking downstream on Manzanita Ave.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		39.758260 °
Category	Rivers, Channels & Designated Flood			-121.795380 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		39.758260 °
Category	Rivers, Channels & Designated Flood			-121.795380 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c _ 2012_18			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View

Manzanita Ave. / Down (cont)

Rating **	A	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		39.758260 °
Category	Rivers, Channels & Designated Flood			-121.795380 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_19			

Action/Comments

Inspector Comments: Riprap is visible and appears properly maintained.

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		39.758260 °
Category	Rivers, Channels & Designated Flood			-121.795380 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_20			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Hwy 99 Bridge / Up

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_21			

Action/Comments

Inspector Comments: Minimal scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 1 : CH_2014_NA0060_5_21_20140721_00017.jpg



View upstream of Big Chico Creek at Highway 99.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View				
Hwy 99 Bridge / Up (cont)				
Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_22			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_23			
Action/Comments				
Inspector Comments: No erosion present.				

No Photos

Rating **	A	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_24			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View				
Hwy 99 Bridge / Up (cont)				
Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_25			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.				

No Photos

Check Point / View				
Hwy 99 Bridge / Down				
Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_26			
Action/Comments				
Inspector Comments: Minimal scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2014_NA0060_5_26_20140721_00018.jpg



View downstream of Big Chico Creek at Highway 99.

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_27			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View

Hwy 99 Bridge / Down (cont)

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c _ 2012_28			
Action/Comments				
Inspector Comments: No erosion present.				

No Photos

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c _ 2012_29			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		39.738490 °
Category	Rivers, Channels & Designated Flood			-121.822810 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c _ 2012_30			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View

Esplanade / Up

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_31			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2014_NA0060_5_31_20140721_00019.jpg



This photo is looking upstream from Esplanade Avenue.

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_33			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View

Esplanade / Up (cont)

Rating **	N	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_34			

Action/Comments

Inspector Comments: No revetments present.

No Photos

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_35			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Esplanade / Down

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_36			

Action/Comments

Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded.

Photo 1 of 1 : CH_2014_NA0060_5_36_20140721_00020.jpg



This view is looking downstream from Esplanade Avenue.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View

Esplanade / Down (cont)

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c _ 2012_37			

Action/Comments

Inspector Comments: No shoaling or sedimentation observed.

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c _ 2012_38			

Action/Comments

Inspector Comments: No erosion observed.

No Photos

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c _ 2012_39			

Action/Comments

Inspector Comments: No revetments present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View				
Esplanade / Down (cont)				
Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		39.731810 °
Category	Rivers, Channels & Designated Flood			-121.841870 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_40			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Hwy 32 / Up				
Rating **	A	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		39.725860 °
Category	Rivers, Channels & Designated Flood			-121.851360 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_41			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2014_NA0060_5_41_20140721_00021.jpg



This photo is looking upstream from Highway 32 bridge.

Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		39.725860 °
Category	Rivers, Channels & Designated Flood			-121.851360 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_42			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View				
Hwy 32 / Up (cont)				
Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		39.725860 °
Category	Rivers, Channels & Designated Flood			-121.851360 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_43			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	N	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		39.725860 °
Category	Rivers, Channels & Designated Flood			-121.851360 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_44			
Action/Comments				
Inspector Comments: No revetments present.				

No Photos

Rating **	A	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		39.725860 °
Category	Rivers, Channels & Designated Flood			-121.851360 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_45			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View

Hwy 32 / Down

Rating **	A	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		39.725860 °
Category	Rivers, Channels & Designated Flood			-121.851360 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_46			

Action/Comments

Inspector Comments: Moderate vegetation on north bank. The flow is not impeded.

Photo 1 of 1 : CH_2014_NA0060_5_46_20140721_00022.jpg



This photo is looking downstream from Highway 32.

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		39.725860 °
Category	Rivers, Channels & Designated Flood			-121.851360 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_47			

Action/Comments

Inspector Comments: No shoaling or sedimentation observed.

No Photos

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		39.725860 °
Category	Rivers, Channels & Designated Flood			-121.851360 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_48			

Action/Comments

Inspector Comments: No erosion observed.

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View				
Hwy 32 / Down (cont)				
Rating **	N	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		39.725860 °
Category	Rivers, Channels & Designated Flood			-121.851360 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_49			
Action/Comments				
Inspector Comments: No revetments present.				

No Photos

Rating **	A	Issue No.	50	GPS Lat/Long
Issue Type +	Ma	Location *		39.725860 °
Category	Rivers, Channels & Designated Flood			-121.851360 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c_2012_50			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Mud Creek at River Rd / Up				
Rating **	A	Issue No.	51	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_5_c_2012_51			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2014_NA0060_5_51_20140721_00023.jpg



This photo is looking upstream from River Road at Mud Creek, near the confluence with the Sacramento River.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View

Mud Creek at River Rd / Up (cont)

Rating **	A	Issue No.	52	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_52			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	53	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c_2012_53			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	M	Issue No.	54	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c_2012_54			
Action/Comments				
Inspector Comments: Riprap is covered with vegetation.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View			
Mud Creek at River Rd / Up (cont)			
Rating **	A	Issue No.	55
Issue Type +	Ma	Location *	39.704580 °
Category	Rivers, Channels & Designated Flood		-121.939320 °
Item	Encroachments		
DWR ID	DWR_NA0060_5_c_2012_55		
Action/Comments			
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.			

No Photos

Check Point / View			
Mud Creek at River Rd / Down			
Rating **	A	Issue No.	56
Issue Type +	Ma	Location *	39.704580 °
Category	Rivers, Channels & Designated Flood		-121.939320 °
Item	Vegetation & Obstructions		
DWR ID	DWR_NA0060_5_c_2012_56		
Action/Comments			
Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded.			

Photo 1 of 1 : CH_2014_NA0060_5_56_20140721_00024.jpg



This photo is looking downstream from the River Road bridge, near the confluence of the Sacramento River.

Rating **	A	Issue No.	57	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_5_c_2012_57			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Big Chico Creek	13.00	07/16/2014 07/16/2014	Matthew Hoffman

Check Point / View

Mud Creek at River Rd / Down (cont)

Rating **	A	Issue No.	58	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_5_c _ 2012_58			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	A	Issue No.	59	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Revetments			
DWR ID	DWR_NA0060_5_c _ 2012_59			
Action/Comments				
Inspector Comments: Riprap is covered with vegetation.				

No Photos

Rating **	A	Issue No.	60	GPS Lat/Long
Issue Type +	Ma	Location *		39.704580 °
Category	Rivers, Channels & Designated Flood			-121.939320 °
Item	Encroachments			
DWR ID	DWR_NA0060_5_c _ 2012_60			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance**Unit Cover Sheet****2014 Channel Inspection Results****DWR Sutter Maintenance Yard**

Channel
Lindo Channel & Sandy Gulch

Channel Rating	A
Date of Inspection	07/15/2014
DWR Inspector	Matthew Hoffman
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

Diversion Structure / Up

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_1			

Action/Comments

Inspector Comments: Minimal, scattered obstructions and small trees. The flow is not impeded.

Photo 1 of 1 : CH_2014_NA0060_6_1_20140721_00025.jpg



This is a view of the upstream side of the Lindo Control Structure.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_2			

Action/Comments

Inspector Comments: No shoaling or sedimentation observed.

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_3			

Action/Comments

Inspector Comments: No head cutting or horizontal deviation observed.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

Diversion Structure / Up (cont)

Rating **	N	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_4			

Action/Comments

Inspector Comments: This item does not apply to this inspection.

No Photos

Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_5			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Diversion Structure / Down

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_6			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 1 : CH_2014_NA0060_6_6_20140721_00023.jpg



This view is of the downstream side of the control structure.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

Diversion Structure / Down (cont)

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c _ 2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_8			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_9			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View				
Diversion Structure / Down (cont)				
Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		39.761590 °
Category	Rivers, Channels & Designated Flood			-121.797320 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_10			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Manzanita Ave / Up				
Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		39.760510 °
Category	Rivers, Channels & Designated Flood			121.802070 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_11			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2014_NA0060_6_11_20140721_00026.jpg



This view is looking upstream from Manzanita Avenue.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		39.760510 °
Category	Rivers, Channels & Designated Flood			121.802070 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_12			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View				
Manzanita Ave / Up (cont)				
Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		39.760510°
Category	Rivers, Channels & Designated Flood			121.802070°
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c _ 2012_13			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

No Photos

Rating **	N	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		39.760510 °
Category	Rivers, Channels & Designated Flood			121.802070 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_14			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

No Photos

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		39.760510 °
Category	Rivers, Channels & Designated Flood			121.802070 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c _ 2012_15			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

Manzanita Ave / Down

Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		39.760510 °
Category	Rivers, Channels & Designated Flood			121.802070 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_16			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2014_NA0060_6_16_20140721_00027.jpg



This view is looking downstream from Manzanita Ave.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		39.760510 °
Category	Rivers, Channels & Designated Flood			121.802070 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		39.760510 °
Category	Rivers, Channels & Designated Flood			121.802070 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_18			
Action/Comments				
Inspector Comments: Some head cutting or horizontal deviation observed due to high water in past years.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View				
Manzanita Ave / Down (cont)				
Rating **	N	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		39.760510 °
Category	Rivers, Channels & Designated Flood			121.802070 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_19			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		39.760510 °
Category	Rivers, Channels & Designated Flood			121.802070 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_20			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Bike Path Bridge at Madrone Ave / Up				
Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			121.814580 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_21			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2014_NA0060_6_21_20140721_00028.jpg



This view is looking up stream from the bike path bridge at the extension of Madrone Avenue.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

Bike Path Bridge at Madrone Ave / Up (cont)

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			121.814580 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_22			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			121.814580 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_23			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	A	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			121.814580 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_24			
Action/Comments				
Inspector Comments: Riprap at the foot of the bridge seems to have slid down towards the channel in previous high water events.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

Bike Path Bridge at Madrone Ave / Up (cont)

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			121.814580 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_25			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Bike Path Bridge at Madrone Ave / Down

Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			121.814580 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_26			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 1 : CH_2014_NA0060_6_26_20140721_00029.jpg



This photo is looking downstream from the bike path at the extension of Madrone Avenue.

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			121.814580 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_27			

Action/Comments

Inspector Comments: No shoaling or sedimentation observed.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

Bike Path Bridge at Madrone Ave / Down (cont)

Rating **	M	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			121.814580 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_28			
Action/Comments				
Inspector Comments: There is some minor bank erosion.				

No Photos

Rating **	A	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			121.814580 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_29			
Action/Comments				
Inspector Comments: Riprap at the foot of the bridge seems to have slid down towards the channel in previous high water events.				

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		39.755400 °
Category	Rivers, Channels & Designated Flood			121.814580 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_30			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

Mariposa Ave / Up

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_31			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2014_NA0060_6_31_20140721_00030.jpg



This view is looking upstream from the bridge at Mariposa Avenue.

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_32			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_33			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

Mariposa Ave / Up (cont)

Rating **	N	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_34			

Action/Comments

Inspector Comments: This item does not apply to this inspection.

No Photos

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_35			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Mariposa Ave / Down

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_36			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 1 : CH_2014_NA0060_6_36_20140721_00031.jpg



This photo is looking downstream from the Mariposa Avenue bridge.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View				
Mariposa Ave / Down (cont)				
Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_37			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_38			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				
No Photos				

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_39			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View				
Mariposa Ave / Down (cont)				
Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		39.752730 °
Category	Rivers, Channels & Designated Flood			-121.824560 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_40			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
5th Ave / Up				
Rating **	A	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		39.752332 °
Category	Rivers, Channels & Designated Flood			-121.829199 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_41			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2014_NA0060_6_41_20140721_00032.jpg



This photo is looking upstream from 5th Ave.

Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		39.752332 °
Category	Rivers, Channels & Designated Flood			-121.829199 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_42			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation observed.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View				
5th Ave / Up (cont)				
Rating **	M	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		39.752332 °
Category	Rivers, Channels & Designated Flood			-121.829199 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c _ 2012_43			
Action/Comments				
Inspector Comments: Erosion around bridge footing and south bank of channel.				

No Photos

Rating **	A	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		39.752332 °
Category	Rivers, Channels & Designated Flood			-121.829199 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_44			
Action/Comments				
Inspector Comments: Existing riprap protecting is properly maintained and is undamaged. Riprap clearly visible				

No Photos

Rating **	A	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		39.752332 °
Category	Rivers, Channels & Designated Flood			-121.829199 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c _ 2012_45			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

5th Ave / Down

Rating **	A	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		39.752332 °
Category	Rivers, Channels & Designated Flood			-121.829199 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_46			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2014_NA0060_6_46_20140721_00033.jpg



This photo is looking downstream from 5th Ave.

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		39.752332 °
Category	Rivers, Channels & Designated Flood			-121.829199 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_47			
Action/Comments				
Inspector Comments: Minimal shoaling or sedimentation present.				

No Photos

Rating **	M	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		39.752332 °
Category	Rivers, Channels & Designated Flood			-121.829199 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_48			
Action/Comments				
Inspector Comments: Erosion around bridge footing and south bank of channel.				

Photo 1 of 2 : CH_2014_NA0060_6_48_20140630_00011.jpg



Erosion around bridge footing and south bank of channel.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View				
5th Ave / Down (cont)				
Rating **	M	Issue No.	48 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.752332 °
Category	Rivers, Channels & Designated Flood			-121.829199 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_48			
Action/Comments				
Inspector Comments: Erosion around bridge footing and south bank of channel.				

Photo 2 of 2 : CH_2014_NA0060_6_48_20140630_00012.jpg



Erosion around bridge footing and south bank of channel.

Rating **	A	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		39.752332 °
Category	Rivers, Channels & Designated Flood			-121.829199 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_49			
Action/Comments				
Inspector Comments: Existing riprapprotection is properly maintained and is undamaged. Riprap clearly visible.				

No Photos

Rating **	A	Issue No.	50	GPS Lat/Long
Issue Type +	Ma	Location *		39.752332 °
Category	Rivers, Channels & Designated Flood			-121.829199 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_50			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

Esplanade / Up

Rating **	A	Issue No.	51	GPS Lat/Long
Issue Type +	Ma	Location *		39.749380 °
Category	Rivers, Channels & Designated Flood			-121.854400 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_51			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH_2014_NA0060_6_51_20140630_00013.jpg



Concrete cracking on south side wing wall upstream of Esplanade Ave.

Photo 2 of 2 : CH_2014_NA0060_6_51_20140630_00014.jpg



This view is looking upstream from Esplanade Avenue bridge.

Rating **	M	Issue No.	57	GPS Lat/Long
Issue Type +	Ma	Location *		39.749380 °
Category	Rivers, Channels & Designated Flood			-121.854400 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_57			

Action/Comments

Inspector Comments: Shoaling present on the upstream side underneath the bike crossing bridge.

No Photos

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View				
Esplanade / Up (cont)				
Rating **	A	Issue No.	53	GPS Lat/Long
Issue Type +	Ma	Location *		39.749380 °
Category	Rivers, Channels & Designated Flood			-121.854400 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_53			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

No Photos

Rating **	N	Issue No.	54	GPS Lat/Long
Issue Type +	Ma	Location *		39.749380 °
Category	Rivers, Channels & Designated Flood			-121.854400 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_54			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

No Photos

Rating **	A	Issue No.	55	GPS Lat/Long
Issue Type +	Ma	Location *		39.749380 °
Category	Rivers, Channels & Designated Flood			-121.854400 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_55			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

Esplanade / Down

Rating **	A	Issue No.	56	GPS Lat/Long
Issue Type +	Ma	Location *		39.749380 °
Category	Rivers, Channels & Designated Flood			-121.854400 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c _ 2012_56			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Rating **	A	Issue No.	56 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.749380 °
Category	Rivers, Channels & Designated Flood			-121.854400 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c _ 2012_56			

Photo 1 of 2 : CH_2014_NA0060_6_56_20140721_00034.jpg



This photo is looking downstream from Esplanade Avenue bridge.

Photo 2 of 2 : CH_2014_NA0060_6_56_20140630_00016.jpg



Concrete cracking on south side wing wall downstream of Esplanade Ave.

Rating **	A	Issue No.	52	GPS Lat/Long
Issue Type +	Ma	Location *		39.749380 °
Category	Rivers, Channels & Designated Flood			-121.854400 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c _ 2013_52			
Action/Comments				
Inspector Comments: Minimal shoaling and sedimentation present.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View				
Esplanade / Down (cont)				
Rating **	A	Issue No.	58	GPS Lat/Long
Issue Type +	Ma	Location *		39.749380 °
Category	Rivers, Channels & Designated Flood			-121.854400 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c _ 2012_58			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed both there are cracks in the south wing wall.				

No Photos

No Photos

Rating **	N	Issue No.	59	GPS Lat/Long
Issue Type +	Ma	Location *		39.749380 °
Category	Rivers, Channels & Designated Flood			-121.854400 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_59			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

No Photos

Rating **	A	Issue No.	60	GPS Lat/Long
Issue Type +	Ma	Location *		39.749380 °
Category	Rivers, Channels & Designated Flood			-121.854400 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c _ 2012_60			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

Hwy 32 / Up

Rating **	A	Issue No.	61	GPS Lat/Long
Issue Type +	Ma	Location *		39.741190 °
Category	Rivers, Channels & Designated Flood			-121.881380 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c _ 2012_61			
Action/Comments				
Inspector Comments: Vegetation exists but does not impede the flow.				

Photo 1 of 1 : CH_2014_NA0060_6_61_20140721_00035.jpg



This view is looking upstream from the Highway 32, Nord Avenue bridge.

Rating **	A	Issue No.	62	GPS Lat/Long
Issue Type +	Ma	Location *		39.741190 °
Category	Rivers, Channels & Designated Flood			-121.881380 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c _ 2012_62			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	63	GPS Lat/Long
Issue Type +	Ma	Location *		39.741190 °
Category	Rivers, Channels & Designated Flood			-121.881380 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c _ 2012_63			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View				
Hwy 32 / Up (cont)				
Rating **	A	Issue No.	64	GPS Lat/Long
Issue Type +	Ma	Location *		39.741190 °
Category	Rivers, Channels & Designated Flood			-121.881380 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_64			
Action/Comments				
Inspector Comments: Revetment is present but due to vegetation not all of it is visible.				

No Photos

Rating **	A	Issue No.	65	GPS Lat/Long
Issue Type +	Ma	Location *		39.741190 °
Category	Rivers, Channels & Designated Flood			-121.881380 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_65			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Hwy 32 / Down				
Rating **	A	Issue No.	66	GPS Lat/Long
Issue Type +	Ma	Location *		39.741190 °
Category	Rivers, Channels & Designated Flood			-121.881380 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_66			
Action/Comments				
Inspector Comments: Vegetation exists but does not impede the flow.				

Photo 1 of 1 : CH_2014_NA0060_6_66_20140721_00036.jpg



This photo is looking downstream from Highway 32, Nord Avenue bridge.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View				
Hwy 32 / Down (cont)				
Rating **	A	Issue No.	67	GPS Lat/Long
Issue Type +	Ma	Location *		39.741190 °
Category	Rivers, Channels & Designated Flood			-121.881380 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_67			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	68	GPS Lat/Long
Issue Type +	Ma	Location *		39.741190 °
Category	Rivers, Channels & Designated Flood			-121.881380 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_68			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	A	Issue No.	69	GPS Lat/Long
Issue Type +	Ma	Location *		39.741190 °
Category	Rivers, Channels & Designated Flood			-121.881380 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_69			
Action/Comments				
Inspector Comments: Revetment is present but due to vegetation not all of it is visible.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View				
Hwy 32 / Down (cont)				
Rating **	A	Issue No.	70	GPS Lat/Long
Issue Type +	Ma	Location *		39.741190 °
Category	Rivers, Channels & Designated Flood			-121.881380 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_70			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Oak Ave. / Up				
Rating **	A	Issue No.	71	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_71			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation.				

Photo 1 of 1 : CH_2014_NA0060_6_71_20140721_00037.jpg



This photo is looking upstream from Oak Ave. bridge.

Rating **	A	Issue No.	72	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_72			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

*** Location**
LS : Land Side
WS : Water Side
CR : Crown

**** Rating**
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View				
Oak Ave. / Up (cont)				
Rating **	A	Issue No.	73	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_73			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	74	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_74			
Action/Comments				
Inspector Comments: No revetments present.				

No Photos

Rating **	A	Issue No.	75	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_75			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

Oak Ave. / Down

Rating **	A	Issue No.	76	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_76			
Action/Comments				
Inspector Comments: scattered obstructions and vegetation.				

Photo 1 of 1 : CH_2014_NA0060_6_76_20140721_00038.jpg



This photo is looking downstream from Oak Ave. bridge.

Rating **	A	Issue No.	77	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_77			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	78	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_78			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

Oak Ave. / Down (cont)

Rating **	N	Issue No.	79	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_79			

Action/Comments

Inspector Comments: No revetments present.

No Photos

Rating **	A	Issue No.	80	GPS Lat/Long
Issue Type +	Ma	Location *		39.735560 °
Category	Rivers, Channels & Designated Flood			-121.890970 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_80			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Grape Way / Up

Rating **	A	Issue No.	81	GPS Lat/Long
Issue Type +	Ma	Location *		39.722700 °
Category	Rivers, Channels & Designated Flood			-121.912520 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_81			

Action/Comments

Inspector Comments: Scattered obstructions and vegetation.

Photo 1 of 1 : CH_2014_NA0060_6_81_20140721_00039.jpg



This photo is looking upstream at the channel from the Grape Way bridge.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View

Grape Way / Up (cont)

Rating **	A	Issue No.	82	GPS Lat/Long
Issue Type +	Ma	Location *		39.722700 °
Category	Rivers, Channels & Designated Flood			-121.912520 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c _ 2012_82			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	83	GPS Lat/Long
Issue Type +	Ma	Location *		39.722700 °
Category	Rivers, Channels & Designated Flood			-121.912520 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c _ 2012_83			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	A	Issue No.	84	GPS Lat/Long
Issue Type +	Ma	Location *		39.722700 °
Category	Rivers, Channels & Designated Flood			-121.912520 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c _ 2012_84			
Action/Comments				
Inspector Comments: Revetments are in place and maintained				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View				
Grape Way / Up (cont)				
Rating **	A	Issue No.	85	GPS Lat/Long
Issue Type +	Ma	Location *		39.722700 °
Category	Rivers, Channels & Designated Flood			-121.912520 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_85			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Grape Way / Down				
Rating **	A	Issue No.	86	GPS Lat/Long
Issue Type +	Ma	Location *		39.722700 °
Category	Rivers, Channels & Designated Flood			-121.912520 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_6_c_2012_86			
Action/Comments				
Inspector Comments: Scattered obstructions and vegetation.				

Photo 1 of 1 : CH_2014_NA0060_6_86_20140721_00040.jpg



This view is looking downstream at the channel at the Grape Way bridge.

Rating **	A	Issue No.	87	GPS Lat/Long
Issue Type +	Ma	Location *		39.722700 °
Category	Rivers, Channels & Designated Flood			-121.912520 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_6_c_2012_87			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Lindo Channel & Sandy Gulch	12.00	07/15/2014 07/15/2014	Matthew Hoffman

Check Point / View				
Grape Way / Down (cont)				
Rating **	A	Issue No.	88	GPS Lat/Long
Issue Type +	Ma	Location *		39.722700 °
Category	Rivers, Channels & Designated Flood			-121.912520 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_6_c_2012_88			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

No Photos

Rating **	A	Issue No.	89	GPS Lat/Long
Issue Type +	Ma	Location *		39.722700 °
Category	Rivers, Channels & Designated Flood			-121.912520 °
Item	Revetments			
DWR ID	DWR_NA0060_6_c_2012_89			
Action/Comments				
Inspector Comments: Revetments are in place and maintained				

No Photos

No Photos

Rating **	A	Issue No.	90	GPS Lat/Long
Issue Type +	Ma	Location *		39.722700 °
Category	Rivers, Channels & Designated Flood			-121.912520 °
Item	Encroachments			
DWR ID	DWR_NA0060_6_c_2012_90			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Flood Control Project Maintenance**Unit Cover Sheet****2014 Channel Inspection Results****DWR Sutter Maintenance Yard**

Channel
Little Chico Creek

Channel Rating	A
Date of Inspection	07/14/2014
DWR Inspector	Matthew Hoffman
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Little Chico Ck Control Structure / Up

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		39.733890 °
Category	Rivers, Channels & Designated Flood			-121.771940 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_1			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions and vegetation. The flow is not impeded.				

Photo 1 of 1 : CH_2014_NA0060_12_1_20140721_00017.jpg



This is the upstream side at the Little Chico Control Structure.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		39.733890 °
Category	Rivers, Channels & Designated Flood			-121.771940 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_2			
Action/Comments				
Inspector Comments: There is shoaling and sedimentation, the flow is not impeded.				

No Photos

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		39.733890 °
Category	Rivers, Channels & Designated Flood			-121.771940 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_3			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Little Chico Ck Control Structure / Up (cont)

Rating **	A	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		39.733890 °
Category	Rivers, Channels & Designated Flood			-121.771940 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2013_4			

Action/Comments

Inspector Comments: Unwanted vegetation needs to be removed.

No Photos

Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		39.733890 °
Category	Rivers, Channels & Designated Flood			-121.771940 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_5			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Little Chico Ck Control Structure / Down

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		39.733890 °
Category	Rivers, Channels & Designated Flood			-121.771940 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_6			

Action/Comments

Inspector Comments: Scattered obstructions and vegetation. The flow is not impeded. Willow trees should be removed in the future.

Photo 1 of 1 : CH_2014_NA0060_12_6_20140721_00018.jpg



This photo is looking downstream from the control structure.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Little Chico Ck Control Structure / Down (cont)

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		39.733890 °
Category	Rivers, Channels & Designated Flood			-121.771940 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_7			
Action/Comments				
Inspector Comments: There is shoaling and sedimentation, the flow is not impeded.				

No Photos

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		39.733890 °
Category	Rivers, Channels & Designated Flood			-121.771940 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_8			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	A	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		39.733890 °
Category	Rivers, Channels & Designated Flood			-121.771940 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_9			
Action/Comments				
Inspector Comments: Unwanted vegetation needs to be removed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Little Chico Ck Control Structure / Down (cont)

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		39.733890 °
Category	Rivers, Channels & Designated Flood			-121.771940 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_10			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View


Bruce Rd / Up

Rating **	M	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		39.733020 °
Category	Rivers, Channels & Designated Flood			-121.787580 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_11			

Action/Comments

Inspector Comments: The vegetation obstructed the view of the channel. Flow may be impeded in high water.

Photo 1 of 1 : CH_2014_NA0060_12_11_20140721_00019.jpg



This photo is looking upstream from Bruce Road bridge.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		39.733020 °
Category	Rivers, Channels & Designated Flood			-121.787580 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_12			

Action/Comments

Inspector Comments: No shoaling or sedimentation observed. The vegetation in the channel obstructed the view.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View				
Bruce Rd / Up (cont)				
Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		39.733020 °
Category	Rivers, Channels & Designated Flood			-121.787580 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_13			
Action/Comments				
Inspector Comments: No erosion observed. Vegetation obstructed the view.				

No Photos

No Photos

Rating **	N	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		39.733020 °
Category	Rivers, Channels & Designated Flood			-121.787580 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_14			
Action/Comments				
Inspector Comments: No revetments present.				

No Photos

No Photos

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		39.733020 °
Category	Rivers, Channels & Designated Flood			-121.787580 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_15			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions observed within the project easement area. The vegetation obstructed the view.				

No Photos

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Bruce Rd / Down

Rating **	M	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		39.733020 °
Category	Rivers, Channels & Designated Flood			-121.787580 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_16			

Action/Comments

Inspector Comments: The vegetation obstructed the view of the channel. Flow may be impeded in high water.

Photo 1 of 1 : CH_2014_NA0060_12_16_20140721_00020.jpg



This photo is looking downstream from Bruce Road bridge.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		39.733020 °
Category	Rivers, Channels & Designated Flood			-121.787580 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_17			

Action/Comments

Inspector Comments: No shoaling or sedimentation observed. The vegetation in the channel obstructed the view.

No Photos

Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		39.733020 °
Category	Rivers, Channels & Designated Flood			-121.787580 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_18			

Action/Comments

Inspector Comments: No erosion observed. Vegetation obstructed the view.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Bruce Rd / Down (cont)

Rating **	N	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		39.733020 °
Category	Rivers, Channels & Designated Flood			-121.787580 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_19			

Action/Comments

Inspector Comments: No revetments present.

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		39.733020 °
Category	Rivers, Channels & Designated Flood			-121.787580 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_20			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions observed within the project easement area. The vegetation obstructed the view.

No Photos

Check Point / View

Forest Ave / Up

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_21			

Action/Comments

Inspector Comments: Minimal, scattered obstructions and vegetation. The flow does not appear impeded.

Photo 1 of 1 : CH_2014_NA0060_12_21_20140721_00021.jpg



This photo is looking upstream from Forest Avenue bridge.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Forest Ave / Up (cont)

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_22			

Action/Comments

Inspector Comments: Shoaling or sedimentation present, the flow does not appear impeded.

No Photos

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_23			

Action/Comments

Inspector Comments: Moderate erosion on north bank.

No Photos

Rating **	N	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_24			

Action/Comments

Inspector Comments: No revetments present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Forest Ave / Up (cont)

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_25			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Forest Ave / Down

Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_26			

Action/Comments

Inspector Comments: Moderate vegetation observed. Flow may be obstructed in high water.

Photo 1 of 1 : CH_2014_NA0060_12_26_20140721_00022.jpg



This photo is looking downstream from Forest Avenue bridge.

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_27			

Action/Comments

Inspector Comments: Shoaling or sedimentation present, the flow does not appear impeded.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Forest Ave / Down (cont)

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_28			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	N	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_29			
Action/Comments				
Inspector Comments: No revetments present.				

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		39.737400 °
Category	Rivers, Channels & Designated Flood			-121.804530 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_30			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Repair site upstream of Hwy 99 / Up

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_31			
Action/Comments				
Inspector Comments: Scattered vegetation. The flow does not appear impeded.				

Photo 1 of 1 : CH_2014_NA0060_12_31_20140721_00023.jpg



This photo is looking upstream at the erosion repair site, up stream from Highway 99 on Humboldt Road. There is vegetation in the channel, the flow in the channel does not appear to be impeded.

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_33			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View				
Repair site upstream of Hwy 99 / Up (cont)				
Rating **	A	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_34			
Action/Comments				
Inspector Comments: Riprap is visible and appears properly maintained.				

No Photos

No Photos

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_35			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Repair site upstream of Hwy 99 / Down

Rating **	M	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_36			
Action/Comments				
Inspector Comments: There is vegetation in the channel, the flow may be impeded in high water.				

Photo 1 of 1 : CH_2014_NA0060_12_36_20140721_00024.jpg



This photo is looking upstream at the erosion repair site, up stream from Highway 99 on Humboldt Road. There is vegetation in the channel, the flow in the channel does not appear to be impeded.

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_37			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_38			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Repair site upstream of Hwy 99 / Down (cont)

Rating **	A	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_39			

Action/Comments

Inspector Comments: Riprap is visible and appears properly maintained.

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		39.735670 °
Category	Rivers, Channels & Designated Flood			-121.814510 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_40			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Boucher St / Up

Rating **	M	Issue No.	41	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_41			

Action/Comments

Inspector Comments: There is vegetation in the channel and overhanging the channel, the flow does not appear impeded.

Photo 1 of 1 : CH_2014_NA0060_12_41_20140721_00025.jpg



This photo is looking upstream from Boucher Street bridge.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Boucher St / Up (cont)

Rating **	A	Issue No.	42	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_42			

Action/Comments

Inspector Comments: No shoaling or sedimentation observed.

No Photos

Rating **	A	Issue No.	43	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_43			

Action/Comments

Inspector Comments: No erosion observed.

No Photos

Rating **	N	Issue No.	44	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_44			

Action/Comments

Inspector Comments: There was no riprap observed at this site.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Boucher St / Up (cont)

Rating **	A	Issue No.	45	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_45			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

Check Point / View

Boucher St / Down

Rating **	M	Issue No.	46	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_46			

Action/Comments

Inspector Comments: There is vegetation in the channel, overhanging the channel, and arndo the flow does not appear impeded.

Photo 1 of 1 : CH_2014_NA0060_12_46_20140721_00026.jpg



This photo is looking downstream from Boucher Street bridge.

Rating **	A	Issue No.	47	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_47			

Action/Comments

Inspector Comments: No shoaling or sedimentation observed.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Boucher St / Down (cont)

Rating **	A	Issue No.	48	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_48			

Action/Comments

Inspector Comments: No erosion observed.

No Photos

Rating **	N	Issue No.	49	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_49			

Action/Comments

Inspector Comments: No riprap observed of this site.

No Photos

Rating **	A	Issue No.	50	GPS Lat/Long
Issue Type +	Ma	Location *		39.730240 °
Category	Rivers, Channels & Designated Flood			-121.823800 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_50			

Action/Comments

Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Olive St / Up

Rating **	A	Issue No.	51	GPS Lat/Long
Issue Type +	Ma	Location *		39.726800 °
Category	Rivers, Channels & Designated Flood			-121.829870 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_51			
Action/Comments				
Inspector Comments: There is vegetation in the channel, it does not appear to impeded the flow.				

Photo 1 of 1 : CH_2014_NA0060_12_51_20140721_00027.jpg



This photo is looking upstream from Olive Street bridge.

Rating **	A	Issue No.	52	GPS Lat/Long
Issue Type +	Ma	Location *		39.726800 °
Category	Rivers, Channels & Designated Flood			-121.829870 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_52			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

Rating **	A	Issue No.	53	GPS Lat/Long
Issue Type +	Ma	Location *		39.726800 °
Category	Rivers, Channels & Designated Flood			-121.829870 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_53			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View				
Olive St / Up (cont)				
Rating **	N	Issue No.	54	GPS Lat/Long
Issue Type +	Ma	Location *		39.726800 °
Category	Rivers, Channels & Designated Flood			-121.829870 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_54			
Action/Comments				
Inspector Comments: No riprap observed at this site.				

No Photos

Rating **	A	Issue No.	55	GPS Lat/Long
Issue Type +	Ma	Location *		39.726800 °
Category	Rivers, Channels & Designated Flood			-121.829870 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_55			
Action/Comments				
Inspector Comments: No Trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

Check Point / View				
Olive St / Down				
Rating **	A	Issue No.	56	GPS Lat/Long
Issue Type +	Ma	Location *		39.726800 °
Category	Rivers, Channels & Designated Flood			-121.829870 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_56			
Action/Comments				
Inspector Comments: There is vegetation in the channel, the flow does not appear impeded.				

Photo 1 of 1 : CH_2014_NA0060_12_56_20140721_00028.jpg



This photo is looking downstream from the Olive Street bridge.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Olive St / Down (cont)

Rating **	A	Issue No.	57	GPS Lat/Long
Issue Type +	Ma	Location *		39.726800 °
Category	Rivers, Channels & Designated Flood			-121.829870 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_57			

Action/Comments

Inspector Comments: There is minimal sedimentation in the channel, the flow does not appear impeded.

No Photos

Rating **	A	Issue No.	58	GPS Lat/Long
Issue Type +	Ma	Location *		39.726800 °
Category	Rivers, Channels & Designated Flood			-121.829870 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_58			

Action/Comments

Inspector Comments: No erosion observed.

No Photos

Rating **	N	Issue No.	59	GPS Lat/Long
Issue Type +	Ma	Location *		39.726800 °
Category	Rivers, Channels & Designated Flood			-121.829870 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_59			

Action/Comments

Inspector Comments: No riprap observed at this site.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View				
Olive St / Down (cont)				
Rating **	A	Issue No.	60	GPS Lat/Long
Issue Type +	Ma	Location *		39.726800 °
Category	Rivers, Channels & Designated Flood			-121.829870 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_60			
Action/Comments				
Inspector Comments: There is a structure on the right bank of the channel, no permit found.				

No Photos

Check Point / View				
Broadway St / Up				
Rating **	A	Issue No.	61	GPS Lat/Long
Issue Type +	Ma	Location *		39.724840 °
Category	Rivers, Channels & Designated Flood			-121.833520 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_61			
Action/Comments				
Inspector Comments: There is vegetation in the channel, the flow does not appear impeded.				

Photo 1 of 1 : CH_2014_NA0060_12_61_20140721_00029.jpg



This photo is looking upstream from the Broadway St. bridge.

Rating **	A	Issue No.	62	GPS Lat/Long
Issue Type +	Ma	Location *		39.724840 °
Category	Rivers, Channels & Designated Flood			-121.833520 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_62			
Action/Comments				
Inspector Comments: No shoaling or sedimentation observed.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View				
Broadway St / Up (cont)				
Rating **	A	Issue No.	63	GPS Lat/Long
Issue Type +	Ma	Location *		39.724840 °
Category	Rivers, Channels & Designated Flood			-121.833520 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_63			
Action/Comments				
Inspector Comments: No erosion observed.				

No Photos

Rating **	N	Issue No.	64	GPS Lat/Long
Issue Type +	Ma	Location *		39.724840 °
Category	Rivers, Channels & Designated Flood			-121.833520 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_64			
Action/Comments				
Inspector Comments: No riprap observed.				

No Photos

Rating **	A	Issue No.	65	GPS Lat/Long
Issue Type +	Ma	Location *		39.724840 °
Category	Rivers, Channels & Designated Flood			-121.833520 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_65			
Action/Comments				
Inspector Comments: No encroachments observed at this site.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Broadway St / Down

Rating **	A	Issue No.	66	GPS Lat/Long
Issue Type +	Ma	Location *		39.724840 °
Category	Rivers, Channels & Designated Flood			-121.833520 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_66			

Action/Comments

Inspector Comments: There is vegetation in the channel, the flow does not appear impeded.

Photo 1 of 1 : CH_2014_NA0060_12_66_20140721_00030.jpg



This photo is looking downstream from Broadway St. bridge.

Rating **	A	Issue No.	67	GPS Lat/Long
Issue Type +	Ma	Location *		39.724840 °
Category	Rivers, Channels & Designated Flood			-121.833520 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_67			

Action/Comments

Inspector Comments: No shoaling observed at this site.

No Photos

Rating **	A	Issue No.	68	GPS Lat/Long
Issue Type +	Ma	Location *		39.724840 °
Category	Rivers, Channels & Designated Flood			-121.833520 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_68			

Action/Comments

Inspector Comments: No erosion observed at this site.

No Photos

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Broadway St / Down (cont)

Rating **	N	Issue No.	69	GPS Lat/Long
Issue Type +	Ma	Location *		39.724840 °
Category	Rivers, Channels & Designated Flood			-121.833520 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_69			

Action/Comments

Inspector Comments: No riprap observed at this site.

No Photos

Rating **	A	Issue No.	70	GPS Lat/Long
Issue Type +	Ma	Location *		39.724840 °
Category	Rivers, Channels & Designated Flood			-121.833520 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2013_70			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the easement.

No Photos

Check Point / View

Lone Pine St / Up

Rating **	A	Issue No.	71	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_71			

Action/Comments

Inspector Comments: There is vegetation in the channel, the flow does not appear impeded.

Photo 1 of 1 : CH_2014_NA0060_12_71_20140721_00031.jpg



This photo is looking upstream from Lone Pine Avenue.

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Lone Pine St / Up (cont)

Rating **	A	Issue No.	72	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_72			
Action/Comments				
Inspector Comments: No shoaling observed at this site.				

No Photos

Rating **	A	Issue No.	73	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_73			
Action/Comments				
Inspector Comments: No erosion observed at this site.				

No Photos

Rating **	N	Issue No.	74	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_74			
Action/Comments				
Inspector Comments: No riprap observed at this site.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Lone Pine St / Up (cont)

Rating **	A	Issue No.	75	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_75			

Action/Comments

Inspector Comments: No encroachments observed at this site.

No Photos

Check Point / View

Lone Pine St / Down

Rating **	A	Issue No.	76	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0060_12_c_2012_76			

Action/Comments

Inspector Comments: There is vegetation in the channel, the flow does not appear impeded.

Photo 1 of 1 : CH_2014_NA0060_12_76_20140721_00032.jpg



This photo is looking down stream from Lone Pine Avenue.

Rating **	A	Issue No.	77	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0060_12_c_2012_77			

Action/Comments

Inspector Comments: No shoaling observed at this site.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2014

DWR Sutter Maintenance Yard

Channel	Channel Length	Inspection Start/End	Inspector
Little Chico Creek	8.00	07/14/2014 07/14/2014	Matthew Hoffman

Check Point / View

Lone Pine St / Down (cont)

Rating **	A	Issue No.	78	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0060_12_c_2012_78			

Action/Comments

Inspector Comments: No erosion observed at this site.

No Photos

Rating **	N	Issue No.	79	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Revetments			
DWR ID	DWR_NA0060_12_c_2012_79			

Action/Comments

Inspector Comments: No riprap observed at this site.

No Photos

Rating **	A	Issue No.	80	GPS Lat/Long
Issue Type +	Ma	Location *		39.703260 °
Category	Rivers, Channels & Designated Flood			-121.868470 °
Item	Encroachments			
DWR ID	DWR_NA0060_12_c_2012_80			

Action/Comments

Inspector Comments: No encroachments observed at this site.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement